



- RESTORATION AND PRESERVATION

Water ingress has caused damage and staining to the stonework. Although a large section of the roof has been repaired, further work is needed to prevent water ingress. Cleaning and repairs to substantial areas of stonework are needed. Routine cleaning of the high levels accessible only by specialist scaffolding is also required.



THE PRIOR FOUNDATION
An Education for Life

*Preserving Our
Sacred Heritage*